

SEWER DEPARTMENT TOWN BOARD NOTES

06/ 01 / 2020

Plant system.

We have issues with 2 of our sludge pumps SBR 2 pump has seal leak must be pulled and rebuilt.

SBR 3 pump has high temp alarm on it may be bad sensor in pump or bad Electrical Cable it must be pulled too for repair.

Collection system.

Had a grinder pump go down in white oaks few weeks ago pump was less than year old had electrical issue bad board in it repair was covered by warranty .

Other.

Notes by: John L. Hodge